

KING COUNTY

SITE ID:	Twin Peaks Equipment		Cleanup Site ID: 9794		FS ID: 58128821
Alternate Name(s): Sunbelt Rentals Inc Redmond, SUPER RENT INC, SUPER RENT INC REDMOND, TWIN PEAKS EQUIPMENT					
LOCATION:		WRIA: 8	Lat/Long: 47.667 -122.101		View Vicinity Map
Address:	17950 REDMOND WAY REDMOND 98052		Township 25N	Range 5E	Section 12 Legislative District: 48 Congressional District: 1
STATUS:	Cleanup Started		Rank:	View Site Web Page	View Site Documents
Responsible Unit: Northwest		Site Manager: Musa, Donna		Statute: MTCA	
Is Brownfield?		Has Environmental Covenant?		Is PSI Site?	
NFA Received?		NFA Date:		NFA Reason:	

ASSOCIATED CLEANUP UNIT(s)

culID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
9486	Twin Peaks Equipment	Upland	Independent Action	Cleanup Started		

SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
LUST	5482	LUST - Notification		11/19/1999	11/19/1999			
LUST	5482	LUST - Report Received		1/10/2007	1/11/2007			
LUST	5482	LUST - Report Received		1/31/2000	2/29/2000			
LUST	5482	LUST - Report Received		12/20/1999	1/17/2000			
LUST	5482	LUST - Report Received		10/14/2003	10/15/2003			
LUST	5482	LUST - Report Received		3/25/2014	4/1/2014			
LUST	5482	LUST - Report Received		11/23/2009	11/30/2009			
LUST	5482	LUST - Report Received		7/28/2008	7/30/2008			
LUST	5482	LUST - Report Received		3/21/2006	3/22/2006			
LUST	5482	LUST - Report Received		3/13/2012	3/14/2012			

AFFECTED MEDIA & CONTAMINANTS:
Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Benzene	C		C			

Key:

B - Below Cleanup Level
C - Confirmed Above Cleanup Level
S - Suspected

R - Remediated
RA - Remediated-Above
RB - Remediated-Below

Non-Halogenated Solvents	C		C			
Petroleum-Diesel	C		C			
Petroleum-Gasoline	C		C			

CleanupSiteDetails2014